

EPA NESHAP guidelines for overspray collection in aerospace painting and reworking facilities and industrial painting applications are as follows:

Existing Paint Booths		New Paint Booths	
Particle Size (Microns)	Efficiency	Particle Size (Microns)	Efficiency
LIQUIDS			
>5.7	>90%	>2.0	>95%
>4.1	>50%	>1.0	>80%
>2.2	>10%	>.42	>65%
SOLIDS			
>8.1	>90%	>2.5	>95%
>5.0	>50%	>1.1	>85%
>2.6	>10%	>.70	75%